

State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING



Michael O. Leavitt Governor Ted Stewart

Executive Director
James W. Carter

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340

801-359-3940 (Fax)

Partial: XXX Complete: Exploration:

Inspection Date & Time: <u>6/20/96 / 11:00a.m.-2:00p.m.</u>

INSPECTION REPORT

Date of Last Inspection: 5/8,23/96

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

1. 2. 3. 4.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE SIGNS AND MARKERS TOPSOIL HYDROLOGIC BALANCE:	EVALUATED [_] [XX] [XX]	<u>N/A</u> ∐ ∐ ∐ ∐	COMMENTS L L L [XX]	NOVÆNF
5. 6. 7.	DIVERSIONS DIVERSIONS DIVERSIONS DIVERSIONS DIVERSIONS DIVERSIONS DIVERSIONS DIVERSIONS DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS NONCOAL WASTE	[XX] [XX] [XX] [] [] [XX] [] [] [XX]			
10. 11. 12. 13.	CONTEMPORANEOUS RECLAMATION BACKFILLING AND GRADING REVEGETATION SUBSIDENCE CONTROL				
a b	DRAINAGE CONTROLS OTHER TRANSPORTATION FACILITIES SUPPORT FACILITIES/UTILITY INSTALLATIONS				



INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 6/20/96

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL

The topsoil piles, which are associated with the Tank seam road construction, are developing more vegetation than has been seen in the past. Mr. Reynolds indicated he will install excelsior matting on the higher elevation pile and reseed it this fall. This pile is showing dispersed growth of some fairly well developed grasses.

4b. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The permittee is in the process of cleaning sediment pond "A". Sediment pond "C" still needs to be recertified by Mr. Kim Mangum, P.E.

4c. OTHER SEDIMENT CONTROL MEASURES

Several silt fences at the site need to be cleaned out. The silt fence located in ditch D-2U immediately north of the Hiawatha intake portal has a hole in the filtering material three inches above the high water mark filtration level. This fabric should be replaced. The silt fence located at the bottom of ditch D-15U (at inlet of culvert C-15U) showed evidence of bypassing. Mr. Reynolds immediately repaired this fence.

20. AIR QUALITY PERMIT

During the inspection, it was noted that the roads at the site were in need of watering. Also, it was necessary for Mr. Reynolds to instruct the coal storage area personnel to turn on the water sprays for the piles. High velocity canyon winds were prevalent.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Charles Reynolds (CO-OP)	Marcia Petta (OSM)
Given to: Joe Helfrich (DOGM)	Filed to: Price Field Office
Date: June 26, 1996	

Inspector's Signature: #46

Peter Hess